

เครื่องวัดอุณหภูมิและความชื้น Thermo Hygrometer รุ่น A2000 ยี่ห้อ HUATO

เครื่องวัดอุณหภูมิและความชื้น ในอากาศ รุ่น A2000 มีระบบการแจ้งเตือนด้วยเสียงและไฟ เมื่ออุณหภูมิเกินค่าที่ตั้งไว้ Measurement Range: -20 to +70°C , 10 to 99%RH, หน้าจอ LCD display เหมาะสำหรับใช้ในครัวเรือน, สำนักงาน, โรงแรม, ร้านอาหาร, โรงเรียน, ห้องประชุม, ห้องรอ, โรงพยาบาล, โรงงาน, ห้างสรรพสินค้า, คลังสินค้า, สภาพแวดล้อมในร่ม ฯลฯ



คุณสมบัติของ Thermo Hygrometer รุ่น A2000

- เครื่องวัดอุณหภูมิและความชื้น ดิจิตอล แบบแขวน/ตั้งโต๊ะ
- แสดงอุณหภูมิและความชื้น แบบเรียลไทม์
- แสดงหน่วยอุณหภูมิได้ 2 แบบ คือ °C และ °F
- มีหน่วยความจำสำหรับอุณหภูมิและความชื้น ที่สูง-ต่ำสุด (Min/Max)
- มีระบบสัญญาณแจ้งเตือนเมื่ออุณหภูมิ ความชื้น สูง-ต่ำ เกินค่าที่ตั้งไว้
- ตัวเครื่องขนาด 135 x 124 x 35 มม.
- ช่วงการวัด -20 ถึง + 70 °C, 10 ถึง 99% RH
- หน้าจอ LCD ขนาดใหญ่ 97 x 78 มม.



เครื่องวัดอุณหภูมิและความชื้น Thermo Hygrometer รุ่น A2000

Model	A2000-TH	A2000-TB	A2000-TS
Accuracy	$\pm 0.5^{\circ}\text{C}$ ($\pm 1.8^{\circ}\text{F}$) / $\pm 5\% \text{RH}$	$\pm 0.3^{\circ}\text{C}$ ($\pm 0.6^{\circ}\text{F}$) / $\pm 3\% \text{RH}$	$\pm 0.2^{\circ}\text{C}$ ($\pm 0.4^{\circ}\text{F}$) / $\pm 2\% \text{RH}$
Measurement Range	-20 to $+70^{\circ}\text{C}$ (-4 to $+158^{\circ}\text{F}$) , 0 to 100%RH		
Resolution	0.1 $^{\circ}\text{C}$ / 1%RH		
Battery	9V Block Battery		
Alarm	Buzzer and LED		
Typical battery life	6 months		
LCD display area	97mm * 78mm		
Weight	300g		
Accessories	9V Block Battery		