
## LBT Series Bottle Cap Tester

LBT Series Bottle Cap Testers are designed to measure the torque of bottle caps. Adjustable posts can grip a wide range of bottle shapes and sizes effectively. Simple operation and easy to use, large easy-to-read LCD display, big data memory.

**Features** 

- Clockwise and anticlockwise direction icon indication
- 3 units of measurements: N.m, kgF.cm, lbF.in, automatic conversion
- 0.3% FS high accuracy and high resolution
- 4 modes of measurement: Real time, peak, save, average
- Average mode:calculates average readings over time
- Upper and lower limit setting for tolerance checking with three different colors indicator lamp
- Backlight and buzzer inside, make screen more brightness and overload alarm
- Individual data memory for up to 100 readings
- Power saving mode of automatic shutoff without any operation
- Micro printer inside and print saved data.
- App. display data on the phone via Bluetooth wireless connection
- USB output, export saved data to the data software and view the load graph over time via graph software





## **Specification**

Model	LBT-1	LBT-2	LBT-5	LBT-10				
Capacity	1 N.m	2 N.m	5 N.m	10 N.m				
Resolution	0.0005 N.m	0.001 N.m	0.001 N.m	0.005 N.m				
Accuracy	0.3% FS							
Units	N.m, kgF.cm, lbF.in							
Weight	9 kgs							
Dimension	28×21×20 cm							

The data received software from torque tester

Control Conne Conne I sol		STATE OF THE	Clour	Office	Tel: +9			500	non levit o tact No Per caledifort
	ottle-Cap T	orque test	lois						
COMPA	NV								
DATE	Nm								
POO-	+1.063	P01-	+1.061	P02+	+1.599	P03+	+0.993	P04=	+1.4%
PO5-	+1.702	P06-	+1.274	P07=	-1 344	P08+	+1.483	P09+	+1.750
P10=	+1.374	P11-	+1.214	P1.2-	-1356	P13+	+1.342	Plde	+1964
P15-	+1.731	P16-	+1.817	P17=	-1.679	P18=	+1.359	P19a	-1.663
P20=	1.000	P21=	-1.148	P22#	-1.087	P25+	1.016	P24+	+0.944
P25=	+0.970	P26=	+1.297	P27 m	+0.000	P28=	+0.000	P.29a	+0.000
P30=	+0.000	P31=	+0.000	P3.2+	+0.000	P33-	+0.000	P34=	+0.000
P3S=	+0.000	P36=	+0.000	P37 n	+0.000	P38=	+0.000	P39n	+0.000
P40-	+ 0.000	P41=	= 0.000	P42=	+0.000	P43+	+0.000	P44-	+0.000
P45=	+0.000	P46=	+0.000	P47-	+0.000	P48=	+0.000	P49+	+0.000
P50-	+0.000	P51=	+0.000	P5.2+	+0.000	P53+	+0.000	P54=	+0.000
P55=	+0.000	P56=	+0.000	P57-	+0.000	P58+	-0.000	P59=	+0.000
P60-	+0.000	P61-	+0.000	P62+	+0.000	P63=	+0.000	P64-	+0.000
P65-	+0.000	P66=	+0.000	P67=	+0.000	P68=	·0.000	P69=	+0.000
P70=	+0.000	P71-	+0.000	P72=	+0.000	P73+	+0.000	P74-	+ 0.000
MacForce		1.964							
Min.Force:		0.944							
Average Total	1.389								



Tel: 02 964 8018 | Line ID: @scilution